

CERTIFICATE

CERTIFIED PLAYGROUND SAFETY INSPECTOR

Certificate no. 071



Nordic Playground Institute Denmark hereby certifies:

Snjólaug María Jónsdóttir, born on December 22nd, 1978, has completed the training:

CERTIFIED PLAYGROUND SAFETY INSPECTOR

- having acquired the knowledge and competencies in the understanding of the valid standards mentioned below, including inspection of equipment, reporting, and use of relevant testing equipment.

EN 1176-1	Playground equipment and surfacing - General safety measures and tests
EN 1176-2	Swings - Additional safety measures and testing methods
EN 1176-3	Slides - Additional safety measures and testing methods
EN 1176-4	Cableways - Additional safety measures and testing methods
EN 1176-5	Carousels - Additional safety measures and testing methods
EN 1176-6	Rocking equipment - Additional safety measures and testing
EN 1176-7	Guidance on maintenance, inspection, and operation
EN 1176-10	Fully enclosed playground equipment - Additional measures
EN 1176-11	3-dimensional climbing structures - Additional safety measures
EN 14974	Skateparks – Safety measures
EN 15312	Free access multi-sports equipment
EN 16630	Permanently installed outdoor fitness equipment
EN 16899	Sports and recreational equipment – Parkour
EN 1177	Impact attenuating surfacing – Testing and reporting



Nordic Playground Institute

Initial certification: 2025

This certificate is valid for the following inspections:
Post installation, operational and annual, until:
February 1st, 2028, unless revoked earlier.



Place: Næstved **Date:** February 1st, 2025


Einar Jon Skulason Hansen
Group Chief Executive Officer



NORDIC PLAYGROUND INSTITUTE

Maglemølle 21
DK4700 Naestved, Denmark
Telephone +45 70 70 78 17
Mail: info@nlpi.dk
www.nlpi.dk